

## MY DXB 35m Refit 2021-2022

## Interior

- 1. New ceilings
- 2. New flooring (new marble and carpets)
- 3. New fabrics (cabins)
- 4. New electrical blinds (main / upper salons + master cabin)
- 5. Automation of lights, curtains, AV
- 6. New furniture (sofas, tables, chairs)
- 7. Full refurbishing of crew area (paint, varnishes, mattresses, bathrooms, galley seating area)
- 8. New Miele cooktop in galley
- 9. Additional new dishwasher in upper salon
- 10. New art pieces (salons, corridors, cabins)
- 11. New TVs (2 salons + all cabins)
- 12. Insulation foam (inside bulkheads, technical lockers, bilges)
- 13. Bar tops (new marble)
- 14. All interior design reviewed and refreshed
- 15. Wheelhouse's electronics reviewed and updated
- 16. New surround sound system

## Exterior

- 1. Full paint (hull and superstructure)
- 2. New teak on sundeck
- 3. New teak step to bow area
- 4. New teak on bow area
- 5. New teak on swim platform
- 6. New teak jacuzzi perimeter
- 7. Full teak deck recaulking and sanding
- 8. Converted step lights from spot lights to hidden LED strip lights
- 9. New lighting (ceiling and courtesy)
- 10. All new upholstery (all decks)
- 11. New upper deck extendable dining table + seating area
- 12. Full polishing of stainless-steel items
- 13. New outdoor furniture
- 14. New CCTV system installed
- 15. New IP Camera installed in stern
- 16. New sun awning
- 17. New Seabob F5S

## **Under hull**

- 1. New depth sounder transducer
- 2. New sea lights (underwater lights) supply and installation
- 3. Full sanding of the hull bottom and application of primer + primer antifouling + antifouling